

# TLT Studio Changelog

All notable changes to TLT Studio software will be documented in this file.

Project versioning adheres to [Semantic Versioning \(https://semver.org/spec/v2.0.0.html\)](https://semver.org/spec/v2.0.0.html).

## Version 1.3.1 (2019-01-31)

### Fixed

- fixed inconsistency between real and displayed line number of threshold inspection on image tab

## Version 1.3.0 (2019-01-29)

### Added

- thickness offset parameter setting added to profile processing section of sensor parameters
- added loader indicating loading of sensor parameters for better user experience

### Fixed

- synchronization error when "Set EEPROM bank active" function is used