Studio Changelog

All notable changes to software will be documented in this file.

Project versioning adheres to [Semantic Versioning (https://semver.org/spec/v2.0.0.html)](https://semver.org/spec/v2.0.0.html).

Version 1.13.1 (2023-02-16)

Fixed

- Fixed bug in BMP image save
- Fixed slow repsonse on Sensor search button

Version 1.13.0 (2023-02-15)

Added

- Digital IO - inputs, outputs, leds state visualization on measure, profile and sensor tabs (firmware 3v8+ required)
- Fixed distance/height range multiplication in output settings
- Factory eeprom reset
- Minor UI changes
- Warning when sensor firmware 3v8 or lower is used

Version 1.12.0 (2022-06-07)

Added

- verification sensor firmware 3v7 or higher is used

Version 1.11.0 (2022-05-23)

Added

- added new Edge mode

Fixed

- fixed FW update bug present in version 1.10.0

Version 1.10.0 (2021-03-17)

Added

- added button to download measured stream data

Version 1.9.0 (2021-03-08)

Added

- alert when new sensor model is connected, which requires new SW version (>2.0.0)

Fixed

- fixed slow response of sensor scan function

Version 1.8.1 (2019-07-17)

Fixed

- fixed bug in saving processing area in eeprom when using long range version of sensor (TLE 100-300)

Version 1.8.0 (2019-02-13)

Added

- display values of measured points on profile tab

Fixed

- fixed bug in parameter loading indication

Version 1.7.0 (2019-01-30)

Added

- added loader indicating loading of sensor parameters for better user experience