

# TL Studio Changelog

All notable changes to TL Studio software will be documented in this file.

Project versioning adheres to [Semantic Versioning \(https://semver.org/spec/v2.0.0.html\)](https://semver.org/spec/v2.0.0.html).

## Version 1.12.0 (2022-06-07)

### Added

- verification sensor firmware 3v7 or higher is used

## Version 1.11.0 (2022-05-23)

### Added

- added new Edge mode

### Fixed

- fixed FW update bug present in version 1.10.0

## Version 1.10.0 (2021-03-17)

### Added

- added button to download measured stream data

## Version 1.9.0 (2021-03-08)

### Added

- alert when new sensor model is connected, which requires new SW version (>2.0.0)

### Fixed

- fixed slow response of sensor scan function

## Version 1.8.1 (2019-07-17)

### Fixed

- fixed bug in saving processing area in eeprom when using long range version of sensor (TLE 100-300)

## Version 1.8.0 (2019-02-13)

### Added

- display values of measured points on profile tab

### Fixed

- fixed bug in parameter loading indication

## Version 1.7.0 (2019-01-30)

### Added

- added loader indicating loading of sensor parameters for better user experience